



VEHICLE PARTS WAREHOUSE STOCK COUNT

Case Study: Industrial – Car Manufacturer

A car manufacturer required assistance in **counting specific sections of the warehouse to update the stock on hand levels and bin locations** to ensure pickers could locate the stock when they needed to pick an order

VEHICLE PARTS WAREHOUSE STOCK COUNT

Case Study: Industrial – Car Manufacturer

A Swedish automotive manufacturer of luxury vehicles headquartered in Sweden. The company manufactures and markets sport utility vehicles, station wagons, hatchbacks, sedans and compact executive sedans. In August 1955, exports to the USA began since then, the manufacturer's cars have reached all corners of the globe. In Australia, the car manufacturer also operates a number of spare parts warehouses.



REQUIREMENT

The car manufacturer required assistance in **counting specific sections of the warehouse** where products that had arrived directly from overseas on pallets or crates were stored. **Accurate data would then ensure pickers could locate the stock** when they needed to pick an order. The car manufacturer required RGIS to provide the following:

- **Complete a count** of the sections of the warehouse classified as PELC and VMR
- **Update stock on hand levels and bin locations** for all selected stock
- Provide **variance reports**



SOLUTION

The car manufacturer partnered with RGIS to complete the **vehicle parts stock count project**, and RGIS provided the following:

- **RGIS teams conducted a site visit** to better understand the customer's requirements
- Scheduled a team of **14 experienced RGIS auditors** to count both sections of the warehouse over two days (10 for PELC and 4 for VMR)
- **RGIS teams paired up with the customer's employees** to help assist with troubleshooting and accessing stock codes, as some pallets needed to be maneuvered to access the stock code details
- **An electronic stock file was provided to RGIS**, containing the Part Number, Description, Supplier Id, Department, Main Package Id, Current Location and expected Stock on Hand
- **RGIS loaded the electronic stock file into the handheld scanners** to collect stocktake data and produce reports
- Any items which were not found on the product master stock file were quarantined so that **part numbers could be sourced** and added to the database



RESULTS

The car manufacturer found by outsourcing the **vehicle parts stock count project** to RGIS, the following results were achieved:

- **Accurately counted over 17,000 SKUs and over 11,000 bin locations** across both sections of the warehouse
- Once the initial count was completed and data processed, RGIS produced a **variance report** to indicate any part numbers that were:
 - Captured in a bin location not matching the customer's system
 - Stock quantities not balancing to the expected stock on hand
- Once variances were checked, an **accurate upload data file was provided**
- Many part numbers were found in bin locations that the customer did not know about, which would have made it almost impossible for pickers to find this stock



By partnering with RGIS, the car manufacturer was now able to **ensure pickers could easily locate specific stock**, when they needed to fulfil an order



The results from the RGIS stocktake were **much better than previous in-house stocktakes**, so the customer was very satisfied

© 2021 RGIS. All rights reserved.
RGIS_CS_0281_01

Parts Audit



Accurate Data



Variance Reports



Satisfied Customer



CONTACT **RGIS** TODAY TO SEE HOW **WE CAN HELP YOU**



salesNewZealand@rgis.com



+64 09 309 9191



www.rgisinv.co.nz

RGIS